

1 / 15




FIG. 1A




FIG. 1B



FIG. 2

FIG. 2A

Field Observation Form						
Address		1586 A Street		Building Plan SN		
Unit #	12	Inspector	AR	Roof Plan SN		
Bldg #	7	Supervisor	PR	Unit Plan SN		
Camera #	1935	Date	11/27/98	Elevation Plan SN		
Flash Card #	1933b			Site Map SN		
Observation Serial #	1.1	Evidence Type	S	Comments	Count	Code
	1.2	Window 1	P	Crack in stucco	2	4.13
	1.3	Living Room		Cut in Living Room wall	1	7.2.6
	1.4					
	1.5					
	1.6					
	1.7					
	1.8					
	1.9					
	1.10					
	1.11					
	1.12					
	1.13					
	1.14					
	1.15					
	1.16					
	1.17					
	1.18					
	1.19					
	1.20					
	1.21					

118

1078

4/15




FIG. 2B

5/15




FIG. 3

6/15




FIG. 4

7/15

FIG. 5A

400

404

402

403

450

448

426

460

446 444 442 440 434 436 438 424 430 431 432

Microsoft Access - [Evidence Quick View : Form]

File Edit View Insert Format Records Tools Window Help

Set Criteria

Phase : Unit : Address : Location : Code : Expert : Trade : Subcontractor :

Run Criteria

Reset Criteria

Print Photo

Print Report

Photo Path

Close Form

List Illustrated

View Illustrated

Show Plan

Building

Roof

Unit

Elevation

Site

View Plan

View Photo

Illustrate

Current Record

Serial # RT Date Insp. Type Insp. Date

247.3 RT 7/29/98 V Party wall - vert hung d/W fire tape ok

Phase	Unit	Address	Location	Code	Doc	Code Description	Comments	Y	N	Rating
4		7804 Cliffside	Attic	8.2b	P P01583RT	Firetaping at party wall draft stop provided	Party wall - vert hung d/W fire tape ok			
4		7804 Cliffside	Attic	8.2b	P P01574RT	Firetaping at party wall draft stop provided	party wall no horiz joints			
4		7804 Cliffside	Attic	8.2b	P P01575RT	Firetaping at party wall draft stop provided	party wall final tape complete			
4		7804 Cliffside	Attic	8.2b	P P01576RT	Firetaping at party wall draft stop provided	Vert. Hung GYP taped OK			
4		7804 Cliffside	Attic	8.2b	P P01577RT	Firetaping at party wall draft stop provided	party wall 10" metal sleeve cable pent			
4		7804 Cliffside	Attic	8.2a	P P01577RT	Missing firetaping at party wall draft stop in	1/2 gap at sleeve			
4		7804 Cliffside	Attic	8.2b	P P01584RT	Firetaping at party wall draft stop provided	party wall - vert. Hung D/W.			
4		7804 Cliffside	Attic		N		no gable vent			
4		7804 Cliffside	Attic	8.2b	P P01585RT	Firetaping at party wall draft stop provided	GYP tight to sheathing at roof			
4		7804 Cliffside	Attic	8.2b	P P01587RT	Firetaping at party wall draft stop provided	area sep wall cable pent sealed			
4		7804 Cliffside	Attic	8.2b	P P01586RT	Firetaping at party wall draft stop provided	area sep wall pine pent sealed			
4		7804 Cliffside	Bedroom 2		P P01571RT		Heavy Texture Above Closet			
4		7804 Cliffside	Bedroom 2		P P01570RT		AAMA 101-85 JK-1 (MFG)			
4		7804 Cliffside	Entry	2.4.15a	P P01591RT	Weep screed buried	buried weep 7'			
4		7804 Cliffside	Entry		P P01588RT	Double-Click to select record.	entry soffit no stains			
4		7804 Cliffside	Entry	2.4.15b	P P01589RT	Weep screed missing	weep screen holes open			
4		7804 Cliffside	Entry		P P01569RT		gar man door at entry concrete - same			
4		7804 Cliffside	Exterior		P P01593RT		gable vents 1 ea side of party wall			
4		7804 Cliffside	Exterior		P P01592RT		soffit o/all			

Record: 1 of 30




FIG. 5B



Microsoft Access - [Evidence Print Opt's : Form]

File Edit View Insert Format Records Tools Window Help

Doc. Numbr	AddressCombo2	DefectCl	Description
P01563RT.j	7804 Cliffside	8.2b	Firetaping at party wall draft stop prov
P01574RT.j	7804 Cliffside	8.2b	Firetaping at party wall draft stop prov
P01575RT.j	7804 Cliffside	8.2b	Firetaping at party wall draft stop prov
P01576RT.j	7804 Cliffside	8.2b	Firetaping at party wall draft stop prov
P01577RT.j	7804 Cliffside	8.2b	Firetaping at party wall draft stop prov
P01577RT.j	7804 Cliffside	8.2a	Missing firetaping at party wall draft st
P01584RT.j	7804 Cliffside	8.2b	Firetaping at party wall draft stop prov
P01585RT.j	7804 Cliffside	8.2b	Firetaping at party wall draft stop prov
P01586RT.j	7804 Cliffside	8.2b	Firetaping at party wall draft stop prov
P01587RT.j	7804 Cliffside	8.2b	Firetaping at party wall draft stop prov
P01570RT.j	7804 Cliffside		
P01591RT.j	7804 Cliffside	2.4.15a	Weep screed buried
P01588RT.j	7804 Cliffside		
P01589RT.j	7804 Cliffside	2.4.15b	Weep screed missing
P01569RT.j	7804 Cliffside		
P01593RT.j	7804 Cliffside		

**Photo Option**

- ☐ Current Photo
- ☐ All Records
- ☒ Select Photo(s)

**Field Option**

- ☒ Photo w/Fields
- ☐ Photo w/o Fields

**Selection Rules :**

- Select up to twelve photo(s) or plan(s) per print execution
- Hold down the <SHIFT> key for consecutive selection or deselection
- Hold down the <CTRL> key for non-consecutive selections or deselection

Number of Records Selected: 2 482

**PRINT** **CLOSE**

480

FIG. 5C

10/15




FIG. 6




FIG. 7




FIG. 8

13/15




FIG. 9







FIG. 10

15/15

Evidence Photo Report	
	<p>ObservationDate 6/23/98 Company Perry &amp; Perry InspectorInit RT DefectCode DefectDescription Phase 5 Address 700 Wheat Ridge Lane Unit 201 Building 0 Unit 201 Doc Number P00001RT.jpg Comments Bldg #</p>
	<p>ObservationDate 6/24/98 Company Perry &amp; Perry InspectorInit JP DefectCode DefectDescription Phase 3 Address 7811 Gable Building 0 Unit Doc Number P00002JP.jpg Comments</p>
	<p>ObservationDate 6/23/98 Company Perry &amp; Perry InspectorInit RP DefectCode DefectDescription Phase 5 Address 700 Wheat Ridge Lane UNit 201 Building 0 Unit 201 Doc Number P00002RP.jpg Comments Dormer vent d faxed # 1</p>

Wednesday, December 16, 1998

FIG. 11